

SHUTER®
pioneer of workspace solutions

MS mobile display cart

assembly instructions





SHUTER®
pioneer of workspace solutions

www.theshuter.com info@theshuter.com
Tel:+886-4-23358800


6IT000331801

1. MS mobile display cart assembly 1


2. FO flip out bins assembly 13

3. Assemble square-shape perforated pegboard 16

3 Assemble square-shape perforated pegboard



2.3




Note:
The maximum load capacity of each side is limited to 80kg.

FO accessory
① index card


Casters

Standard casters




x 2 x 2 **A** x 4 **B** x 8 x 1

Optional Heavy-Duty Caster



x 2 x 2 **A** x 4 **B** x 8

Screw package




a x 4 M8 x L45
c x 14 M6 x L45
e x 6 M8
b x 2 M8 x L16
d x 4 M6 x L10
h x 12 M6

Pipe plug



i x 2

Required tools



FO accessory





① index card ② screws

I


The assembly process of MS Mobile display cart with standard casters

1.1-1







2.2




Screws attached with FO flip out bins




FO accessory
② screws




Screw hole




2 FO flip out bins assembly



2.1







Optional :


The assembly process of MS Mobile display cart with optional heavy-duty caster.

1.1-2













1.2






1.11






1.10


c 

h 


1. First, put on loosely screws (c+h) to tighten the top rack.




2. Then, screw it tight with screw cap (h)




1.3


c 

h 






1.4




c




h






1.9




1.8





c

1.5


c 

h 





1.6




b



e





1.7

d



