

This exploded perspective view illustrates the assembly of a mechanical component, likely a bracket or housing. The central part is a main casting (1) with various mounting points. Key sub-assemblies and components are shown with dashed lines indicating their assembly paths:

- Top Left:** A curved arm (8) is secured with a screw (22). Below it, a rectangular plate (13) is attached to a shaft (14) with a nut (15) and a pin (16).
- Top Right:** A small bracket (26) is attached to a plate (28) with a screw (12). A pin (27) is also shown.
- Center:** A pin (29) is shown near a small bracket (30). A screw (3) and a nut (4) are shown near a cylindrical component (2).
- Bottom Left:** A sub-assembly (Fig.2) consisting of a nut (4), a screw (3), and a cylindrical component (2) is shown. Another similar sub-assembly is shown below it.
- Bottom Center:** A sub-assembly (Fig.2) consisting of a nut (4), a screw (3), and a cylindrical component (2) is shown.
- Bottom Right:** A sub-assembly (Fig.2) consisting of a nut (4), a screw (3), and a cylindrical component (2) is shown.
- Assembly Lines:** Two dashed lines, labeled A and B, indicate the assembly paths for the main casting (1). Line A points to the bottom right, and line B points to the top right.
- Other Components:** Various screws (9, 10, 11, 12), nuts (2, 3, 4), and pins (25, 26, 27, 28, 29) are shown throughout the assembly.