


針棒機構(4)

●EX(T)5200(H)(N)(M)

■1本針(1-needle)



G ゲージパーツ表参照
Refer to the gauge parts list.

■2本針(2-needle)

